


AMBITO DE INTERVENCIÓN



Parque Metropolitano




Proportion of households without access to safe water, by sector, Parque Metropolitano, Villa El Salvador, 2008

PORC_AGUA1
 0 ≤ n < 65
 65 ≤ n < 80
 80 ≤ n < 90
 90 ≤ n < 100


SECTOR_INDICATORS

acceso_agua
 insegura
 no aplica
 segura

UNIVERSAL TRANSVERSE MERCATOR (UTM)



Proportion of households without access to safe water in Amp. Aires de Pachacamac, Parque Metropolitano, 2008



acceso_agua

- insegura
- no aplica
- segura

PORC_AGUA1

- 0 <= n < 65
- 65 <= n < 80
- 80 <= n < 90
- 90 <= n < 100

■ SECTOR_INDICATORS

UNIVERSAL TRANSVERSE MERCATOR (UTM)



Proportion of households without access to sanitary toilet, by sector, Parque Metropolitano, Villa El Salvador, 2008

PORC_SIN_BANO


- 0 <= n < 65
- 65 <= n < 80
- 80 <= n < 90
- 90 <= n < 100

acceso_baño



- no aplica
- no tiene
- si tiene

SECTOR_INDICATORS

UNIVERSAL TRANSVERSE MERCATOR (UTM)



Proportion of households without access to sanitary toilet in Amp. Aires de Pachacamac, Parque Metropolitano, 2008



UNIVERSAL TRANSVERSE MERCATOR (UTM)

